,,,,,,,	Туре	Ref #	Hits	Search Text	
1	BRS	S1	3	wall ADJ reinforcement ADJ system	
2	BRS	S2	489	52/506.01.ccls.	
3	BRS	S3	30	reinforce AND (veneer ADJ wall)	
4	BRS	S4	3	"1166250"	
5	BRS	S7	24	(reinforcement ADJ wire) AND veneer	
6	BRS	S5	6	"3964227"	
7	BRS	S6	6	"5138813"	
8	BRS	S8	34762	wire SAME helical	
9	BRS	S9	6137	(wire SAME helical) AND connector	
10	BRS	S13	5	52/512.ccls. AND helical	
11	BRS	S14	24	52/512.ccls. AND fins	
12	BRS	S11	0	52/282.4.ccls. AND helical	
13	BRS	S15	0	"10767803"	
14	BRS	S12	21	52/282.4.ccls. AND wire	
15	BRS	S10	280	52/282.4.ccls.	

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; USOCR	2007/05/23 10:59		
2	US-PGPUB; USPAT; USOCR	2007/05/17 15:09		
3	US-PGPUB; USPAT; USOCR	2007/05/17 15:19		
4	US-PGPUB; USPAT; USOCR	2007/05/17 15:20		
5	US-PGPUB; USPAT; USOCR	2007/05/17 16:28		
6	US-PGPUB; USPAT; USOCR	2007/05/17 16:13		
7	US-PGPUB; USPAT; USOCR	2007/05/17 16:27		
8	US-PGPUB; USPAT; USOCR	2007/05/23 i1:00		
9	US-PGPUB; USPAT; USOCR	2007/05/23 11:09		
11 ()	US-PGPUB; USPAT; USOCR	2007/05/23 11:20		
11	US-PGPUB; USPAT; USOCR	2007/05/23 12:09		
12	US-PGPUB; USPAT; USOCR	2007/05/23 11:10		
13	US-PGPUB; USPAT; USOCR	2007/05/23 12:09		
114	US-PGPUB; USPAT; USOCR	2007/05/23 11:18	,	
115	US-PGPUB; USPAT; USOCR	2007/05/23 11:10		